



**Site-Specific Issues**

- A** Lack of Marked Crosswalks
- B** Lack of Intersection Lighting
- C** Eastern Corner Right Turn Slip Lane

	<b>Issue</b>	<b>Recommendation</b>
<b>A</b>	<b>Lack of marked crosswalks</b> at intersection, resulting in reduced pedestrian conspicuity and safety.	<p><b>Long-Term</b></p> <ul style="list-style-type: none"> <li>Stripe high-visibility crosswalks along western and southern legs of intersection and upgrade existing crosswalks on eastern and northern legs to high-visibility crosswalks</li> <li>When striping crosswalks, construct accessible landings</li> </ul>
<b>B</b>	<b>Lack of lighting</b> at intersection, resulting in reduced pedestrian conspicuity and safety.	<p><b>Long-Term</b></p> <ul style="list-style-type: none"> <li>Install intersection lighting to illuminate crosswalks</li> </ul>
<b>C</b>	<b>Eastern corner right turn slip lane</b> with large radius results in high vehicle turning speeds and unsafe pedestrian crossing conditions.	<p><b>Short-Term</b></p> <ul style="list-style-type: none"> <li>Narrow slip lane to reduce turning traffic speeds by using quick-build temporary materials like paint and flexible delineators</li> </ul> <p><b>Long-Term</b></p> <ul style="list-style-type: none"> <li>Eliminate slip lane and reconstruct curbline of eastern corner with truck apron to accommodate heavy vehicles making right turn</li> </ul>

**Study Area 10: Oak Knoll Drive/Canyon Road Intersection**  
Emerald Hills, CA